















No.	Equipment	Asset tag	Photos	Decision	To who / Where?	Comments
1	Direct heat sealer (Sensory Lab)			Discard		not in working condition; no asset tag
2	Impulse heat sealer	NA		Discard		not in working condition (sparks and smoke reported); no asset tag
3	Glass desiccator jar	NA		Discard		silica gel beads give to A lab; no asset tag
4	Centrifuge holders	NA		Discard		main equipment not available in lab; no asset tag
5	Panasonic microwave oven Dimension 4 MN-CD997S (A Lab)	NA		Discard		should be working; no asset tag; from Analytical lab
6	Fisher Scientific Water bath (A Lab)	NA		Discard		should be working; no asset tag
7	Bosch Dish washer (PD Lab)	NA		Discard		should be working; no asset tag
8	Rotary evaporator	3000000469, 3000000483, 3000000479		Discard		
9	Sieve shaker EFL2000	3000000485		Discard		
10	Polytron	3000000406, 3000000445		Discard		Equipment has not been used for many years; weird smell when the equipment was turned on for testing
11	Electric can seamer (trolley not included)	3000000624		Discard		
12	Jura Coffee Machine (Centros Pantry)	20000710		Discard		Not working; In Centros Store
13	Nespresso Coffee Machine	NA		Discard		Not working; In Centros Store
14	Microwave Oven	NA		Discard		Not working; In Centros Store